



**Vehicle History Report #:** 64577647  
**Report Date:** September 24, 2025 | 11:41 a.m. EDT  
**Report Status:** Complete  
**Reference:** Buy Metro

## 2016 VOLKSWAGEN GOLF SPORTWAGEN S

Wagon | 4 Cylinders | Gas  
3VWC17AU2GM515624  
Country of Assembly: Mexico  
Last Reported Odometer: 252,054 KM

3VWC17AU2GM515624



Accident/Damage Records Found



Last Registered In:  
Nova Scotia (Normal)



22 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)



**This vehicle history report is based on information** (<https://www.carfax.ca/vehicle-history-data>) **that was reported and available to CARFAX Canada as of September 24, 2025** (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# Vehicle History Report



## Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
 2022 Nov 2	<b>Ontario, Canada</b>	
	<b>Claim:</b> Other Damage	\$0.00
	<b>Claim:</b> Unknown	\$0.00



## Registration

-  This vehicle has been registered in the following locations in **Canada** (listed oldest to newest):
- In the province of **Ontario** with **Normal** branding.
  - In the province of **Nova Scotia** with **Normal** branding.

**We checked for:** *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2016 Mar 9		Pfaff Volkswagen Newmarket, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Pre-delivery inspection completed</li> <li>• Battery/charging system checked</li> </ul>
2019 Apr 26		Pfaff Volkswagen Newmarket, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Pre-delivery inspection completed</li> <li>• Maintenance inspection completed</li> <li>• Brakes checked</li> <li>• Brake rotor(s) resurfaced</li> <li>• Fluids checked</li> <li>• Front brake rotor(s) resurfaced</li> <li>• Front brakes serviced</li> <li>• Oil and filter changed</li> <li>• Rear brake pads replaced</li> </ul>

3VWC17AU2GM515624

	ODOMETER	SOURCE	DETAILS
			<ul style="list-style-type: none"> <li>Rear brake rotor(s) replaced</li> <li>Safety inspection performed</li> <li>Vehicle washed/detailed</li> </ul>
2019 May 14		Pfaff Volkswagen Newmarket, Ontario, Canada	<b>Vehicle serviced</b>
2019 May 29	73,586 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Window tint installed</li> <li>Vehicle washed/detailed</li> </ul>
2019 Aug 19	77,754 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	<b>Vehicle serviced</b>
2019 Aug 31		Pfaff Volkswagen Newmarket, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Door weatherstrip repaired</li> <li>Interior trim repaired</li> <li>Radio speaker(s) replaced</li> <li>Vehicle washed/detailed</li> </ul>
2019 Sep 13	89,211 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Engine checked</li> <li>Oil and filter changed</li> <li>Tire condition and pressure checked</li> <li>Vehicle washed/detailed</li> </ul>
2019 Sep 26	90,790 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Vehicle washed/detailed</li> </ul>
2020 Jan 16	105,924 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Decarbon service completed</li> <li>Oil and filter changed</li> <li>Tire condition and pressure checked</li> <li>Vehicle washed/detailed</li> </ul>
2020 Jul 17	121,375 KM	Active Green & Ross Barrie, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Maintenance inspection completed</li> <li>Oil and filter changed</li> </ul>
2020 Aug 21	124,475 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Two tires balanced</li> <li>Two tires mounted</li> <li>Vehicle washed/detailed</li> </ul>
2021 May 27	143,525 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> <li>Tire condition and pressure checked</li> <li>Vehicle washed/detailed</li> </ul>

3VWC17AU2GM515624

	ODOMETER	SOURCE	DETAILS
2021 Jul 14	148,399 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>One tire replaced</li> <li>Vehicle washed/detailed</li> </ul>
2021 Aug 23	149,411 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Vehicle washed/detailed</li> </ul>
2022 Nov 10	189,138 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> <li>Vehicle washed/detailed</li> </ul>
2022 Nov 25		Pfaff Volkswagen Newmarket, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> <li>Vehicle washed/detailed</li> </ul>
2023 Mar 3	201,527 KM	Take 5 Oil Change Bradford, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> </ul>
2023 Jul 8	215,755 KM	Take 5 Oil Change Bradford, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> </ul>
2023 Sep 19	223,778 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oxygen sensor replaced</li> <li>Vehicle washed/detailed</li> </ul>
2023 Nov 29	230,485 KM	Take 5 Oil Change Bradford, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> </ul>
2024 Apr 6	240,589 KM	Take 5 Oil Change Bradford, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> </ul>
2024 Jul 2	252,054 KM	Dewitt Vehicle Sales Stoney Creek, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Airbag system checked</li> <li>Seatbelts checked</li> </ul>



## Open Recalls

Recall #: 20UF | SUCTION JET PUMP    Recall Date: 2024 Feb 16

### Recall Description

The suction jet pump inside the fuel tank is designed to purge fuel from the Evaporative Emissions (EVAP) system. If a specific seal inside an affected suction jet pump fails, the fuel may flow

directly into the EVAP system. If this happens, fuel could accumulate in the EVAP system and may leak through the charcoal canister filter element. Leaking fuel, in the presence of an ignition source, may result in a fire.

**Remedy**

Replace the suction jet pump.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



### Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



### Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Mar 9		Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2016 Mar 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Commercial Vehicle colour noted as gray
2018 May 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2019 Feb 22		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Apr 26		Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2019 May 7	73,575 KM	Independent Source Toronto, Ontario, Canada	Odometer reading	

3WVC17AU2GM515624

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 May 14		Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2019 May 28		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray
2019 May 29	73,586 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2019 Aug 19	77,754 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2019 Aug 31		Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2019 Sep 13	89,211 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2019 Sep 26	90,790 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2020 Jan 16	105,924 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2020 Feb 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jul 17	121,375 KM	Active Green & Ross Barrie, Ontario, Canada	Service Record	Vehicle serviced
2020 Aug 21	124,475 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2021 Apr 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2021 May 27	143,525 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2021 Jul 14	148,399 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced

3WVC17AU2GM515624

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Aug 23	149,411 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2022 Feb 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2022 Nov 2		Insurance Records Ontario, Canada		
2022 Nov 2		Ontario, Canada	Unknown	
2022 Nov 10	189,138 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2022 Nov 25		Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2023 Feb 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2023 Mar 3	201,527 KM	Take 5 Oil Change Bradford, Ontario, Canada	Service Record	Vehicle serviced
2023 Jul 8	215,755 KM	Take 5 Oil Change Bradford, Ontario, Canada	Service Record	Vehicle serviced
2023 Sep 19	223,778 KM	Pfaff Volkswagen Newmarket, Ontario, Canada	Service Record	Vehicle serviced
2023 Nov 29	230,485 KM	Take 5 Oil Change Bradford, Ontario, Canada	Service Record	Vehicle serviced
2024 Feb 16		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 20UF
2024 Apr 6	240,589 KM	Take 5 Oil Change Bradford, Ontario, Canada	Service Record	Vehicle serviced
2024 Jun 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray

3WVC17AU2GM515624

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2024 Jul 2	252,054 KM	Dewitt Vehicle Sales Stoney Creek, Ontario, Canada	Service Record	Vehicle serviced
2024 Aug 1		Motor Vehicle Dept. Nova Scotia, Canada	Canadian Renewal	Registration Issued or Renewed



Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada. <https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.

